

Commentary on candidate 2 evidence

The evidence for this candidate has achieved the following marks for each question of this course assessment component.

Item	Commentary	Mark Awarded	Max Marks
1a(i)	0 marks were awarded as the candidate could not identify a mitre joint.	0	1
1a(ii)	1 mark was awarded for 'doweled butt joint'. The candidate has been awarded the mark as this refers to a dowel joint.	1	1
1a(iii)	0 marks were awarded as the candidate could not identify a bridle joint.	0	1
1b.	0 marks were awarded as the responses provided do not relate to the marking out process.	0	3
1c.	1 mark was awarded for 'plough plane'.	1	1
1d.	4 marks were awarded for correctly identifying and completing the table with either hardwood or softwoods.	4	4
1e.	1 mark was awarded for response 1 referring to 'softwoods grow faster' from the marking instructions.	1	2
1f.	1 mark was awarded for 'varnish'.	1	1
2a.	4 marks were awarded for correctly completing 4 correct answers in the cutting list.	4	6
2b(i)	1 mark was awarded for 'mortice machine'. The candidate was not penalised for the incorrect spelling for mortise.	1	1
2b(ii)	0 marks were awarded as the candidate could not identify a disc sander.	0	1
2c.	0 marks were awarded as the candidate could not identify a rebate plane.	0	1
2d.	0 marks were awarded as the candidate could not identify a belt clamp.	0	1

2e.	1 mark was awarded for 'checking that everything is fitting correctly' as this refers to checking the assembly before gluing.	1	1
2f.	1 mark was awarded for 'PVA glue'.	1	1
2g.	1 mark was awarded for 'coarse'.	1	1
2h.	0 marks were awarded as the candidate did not reference 'to raise the grain'.	0	1
3a(i)	1 mark was awarded for 'pillar drill'.	1	1
3a(ii)	0 marks were awarded. The candidate did not state that the 'forstner bit allows for a flat-bottomed hole'.	0	1
3b.	2 marks were awarded for referring to the following points in the marking instructions – 1. 'ensure all guards are down' 2. 'knowing location of emergency stop on machine' Response 2 is a personal safety check and therefore cannot be awarded a mark.	2	3
3c.	0 marks were awarded as the candidate could not identify a through housing joint.	0	1
3d.	3 marks were awarded for making reference to the following points in the marking instructions - 1. 'saw vertical lines' 2. 'chisel out waste material' 3. 'level off with hand router/pare bottom of joint'	3	3
3e(i)	0 marks were awarded as the candidate could not identify a sliding bevel.	0	1
3e(ii)	0 marks were awarded as the candidate could not describe the use of a sliding bevel. There is no mention of adjusting/setting a range of angles.	0	1
3e(iii)	0 marks were awarded as the candidate could not identify a marking knife.	0	1
3e(iv)	0 marks were awarded as the candidate could not describe the use of a marking knife.	0	1

3f.	0 marks were awarded as the candidate could not explain the purpose of the brass back on the tenon saw.	0	1
4a.	2 marks were awarded in stage 1 for referring to the following points in the marking scheme: 1. 'draw diagonals/mark centre' 2. 'mark circle/octagonal shape' The candidate has used sketches to aid with the answers; this has added clarity to the candidate's description of marking out a blank.	2	2
4b.	2 marks were awarded for 'B – blade' and 'D - adjusting wheel'.	2	4
4c.	0 marks were awarded as the candidate could not identify a face plate.	0	1
4d.	0 marks were awarded as the candidate could not identify a headstock.	0	1
4e(i)	1 mark was awarded for 'gouge'.	1	1
4e(ii)	0 marks were awarded as the candidate could not identify a scraper.	0	1
4f.	1 mark was awarded for candidate correctly selecting box B.	1	1
4g.	1 mark was awarded for referring 'sanding'.	1	3
4h.	3 marks were awarded for referring to the following points in the marking instructions – 1. 'goggles/safety specs/visor' 2. tie hair back/tuck away any loose clothing/ remove loose jewellery' 3. 'wear apron'	3	3
4i.	1 mark was awarded for an appropriate response relating to recycling of material/reducing environmental impact.	1	1
		Total marks - 33	